## **ABSTRACT**

A method of inspecting a workpiece during a production run in which workpieces are supplied to workstations by an autoloader. In accordance with the method, the supply of the workpieces by the autoloader is performed in accordance with a supply control routine. When it is desired to inspect a workpiece in a workstation, the supply control routine is interrupted after its then current cycle and the autoloader is used to move the workpiece to a quality control station. The supply of the workpieces in accordance with the supply control routine is then resumed. While the autoloader is operating in accordance with the supply control routine, the workpiece is inspected. If the workpiece is acceptable, the supply control routine is again interrupted after its then current cycle and the autoloader is used to move the workpiece to an output area. The supply of the workpieces in accordance with the supply control routine is then resumed again.

15

10

5